

Arizona Department of Transportation


Emergency Rehabilitation of I-10 Mescal Road TI UP

Navaphan Viboolmate, PE
ADOT Bridge Group Design Section Leader

Arizona Fire Damaged Bridges in the last 15 years

- I-10 Oglesby Road Ramp C UP in 1998
- SR 260 Gordon Canyon Bridge in 1998
- I-15 Virgin River BR #7 in 2001
- SR 87 Slate Creek RCB in 2003 and 2007
- I-10 335th Ave UP in 2006
- I-17 Union Hills Drive TI OP in 2006
- I-10 Hassayampa River Bridge EB in 2008
- SR 95 Bill Williams River Bridge in 2006
- I-10 Mescal Road TI UP in 2011

State Milepost System



I-15 Virgin River BR # 7

SR 95 Bill Williams River Bridge

SR 260 Gordon Canyon Bridge

I-17 Union Hills Drive TI OP

SR 87 Slate Creek RCB

I-10 355th Ave UP

I-10 Hassayampa River Bridge EB

I-10 Oglessby Road Ramp

I-10 Mescal Road TI UP MP 297.17

Mescal Road TI UP Background

- Built 1959
 - 5- Span Steel Girder
- Barrier Replacement 1993
- Sidewalk Widening 2003
 - 6 ft. Sidewalk on the east side
- Heat Straightening Jan 2011

Presentation Overview

- Damage Assessments
- Emergency Repairs
- Project Schedule
- Design
- Construction

Fire Incident


- March 15, Approximate 11:00 pm
- Two semi-trucks collided under the bridge
- Magnesium fire lasted approximately 6 hours



Special Damage Inspection

- Approximately 6" upward deflection at pier 1
- Approximately 2" Lateral deflection
- Concrete spalls from columns and pier cap














Damage Assessments

- Material Properties
- Effects of heat residuals




Figure 2.1. Reduction of steel yield strength with temperature (Astaneh-Asl et al. 2009)




Figure 2.2. Reduction in concrete compressive strength with temperature (Astaneh-Asl et al. 2009)




Figure 2.3. Reduction in strength of prestressing steel and high strength alloy bars with temperature (Astaneh-Asl et al. 2009)




Figure 2.4. Reduction in strength of bolts, welds, reinforcing bars with temperature
(Astaneh-Asl et al. 2009)

Conclusions


- Steel Girders have to be replaced
- Replace all pier caps
- Replace columns at pier 1


Emergency Repairs

- Install Temporary Concrete Barrier around the area
- Install Pedestrian Fence
- Set up a detour for locals
- Deck demolition
- Remove steel girders
- Remove south pier cap and columns









Friday April 8, 2011 (24 days after the incident)
















Project Schedule

- Design 4 weeks
- Bid advertisement April 2011
- Finish Construction by September 10, 2011

Critical Path




Design



Design

- Precast-Prestressed Concrete Box Beam
 - Design spans 31',55',47',55', and 28'
 - Initial Concrete Strength 4,500 psi
 - 28-day Concrete Strength 5,500 psi
 - Minimum strands = 12
 - Maximum strand = 18
 - Precast overhang and barrier Strength 4,500 psi

Integral Overhang and Barrier



Results

- Project advertisement April 29
- Bid opening May 11, Design Bid process
- Contract time 130 days
- Vastco, INC Low bidder \$956,000
- Royden Construction for Precastor Start June
- Construction Start July
- Construction Completed September

Construction

- Began July
- Finished September



























End

Question?

