



Repair of A Large Diameter Non-Redundant Drilled Shaft

2017 Western Bridge Engineers' Seminar

September 7, 2017

Alan Marchman, PE and Kuan Go, PE, SE



Project Description

- Honolulu High Capacity Transit Corridor Project (HHCTP)
 - Owner: Honolulu Authority For Rapid Transportation (HART)
 - Contractor: Kiewit Infrastructure West, Inc.
 - Lead Designer: HNTB
 - Design Team: FIGG, SWI
 - Shaft Testing: Applied Foundations Technology (AFT)


- HNTB Delivered Design For First 10 Miles Under 2 Contracts (\$669M & \$392M)






Design Features


- 437 Spans
- 2 Balanced Cantilever Interstate Crossings
- 457 Piers
- Single Column On Single Shafts





Drilled Shaft Design


- Varying Geology Required Close Coordination With Geotechnical





Drilled Shaft Design

- Seismic Region - Capacity Protected Members
- Rebar Grades 60, 75, And 80, Up To Size No. 18
- Transverse Spiral Reinforcing
- Concrete Strength = 4,000 Psi
- Diameters 7 Ft. To 8.2 Ft.
- Lengths 30' To 120'
- Cased And Uncased Construction



Design Role During Construction

- Shaft QA Utilized Cross-hole Sonic Logging (CSL) Testing (ASTM D6760)
- Acceptance Of Shaft Based On CSL Results And Construction Logs
- Review Criteria Per Project Specification 31 63 30 Section 3.13.G:

Drilled shafts with velocity reductions exceeding 20% in an area between half a shaft diameter below the shaft construction joint, and one foot above the shaft tip shall be evaluated and tracked in an NCR per 3.13.H.

- Previous Shafts Repaired, Typically With High Pressure Grouting Through Core Holes.

Design Role During Construction


The image shows the cover of a report from the U.S. Department of Transportation Federal Highway Administration. It includes the agency logo, publication number (FHWA-NHI-10-016), date (May 2010), and course number (NHI Course No. 132014). The title is 'Drilled Shafts: Construction Procedures and LRFD Design Methods'. It also mentions it was developed following AASHTO LRFD Bridge Design Specifications, 4th Edition, 2007, with 2008 and 2009 Interims. At the bottom, there are two small photographs: one showing a construction site with a large structure being built, and another showing a close-up of a drilled shaft.

- Simplified Relationship
- Calibrated With Break Data
- Quickly Check Models

$$f'_c{}_{Mod} \cong f'_c(1 - VR^2)$$


- Relationship Between Concrete Strength And Velocity Reductions:

$$f'_c \propto VR^2$$




Shaft 235 Repair: Initial Report

- CSL Reported Velocity Reductions >50% In Critical Regions About 13.5 Feet Deep




Shaft 235 Repair: Initial Report

- Cored Anomalous Areas Showed Non-homogenous Concrete




Shaft 235 Repair: Challenges

- Small Working Footprint
- Erection Truss Schedule Demands
- Long Lead Times & High Costs For Moving Materials And Equipment On Island
- High Water Table
- Non-redundant Shaft Means Repaired Shaft Must Meet Original Design Criteria



Shaft 235 Repair: The Process




Shaft 235 Repair: Options



- Material Replacement
- Hydro-demolition And High Pressure Grouting
- Innovative Micropile Installation
- “Sister” Shafts With Cap

Shaft 235 Repair: Options




- Hydro-demolition And High Pressure Grouting
 - Successful At Other Shafts
 - Anomaly Too Large, Risk Pressure Loss
 - QA Difficulties



Shaft 235 Repair: Options

■ Innovative Micropile Installation


- Field Tested For Bond
- Modeled In Fb-pier
- Lacked Shear Capacity



Before test...concrete surface has been ground smooth and new jack chair with plates distribute load to concrete.

Shaft 235 Repair: Options


- “Sister” Shafts With Cap
 - Limited Footprint
 - Load Distribution Impacts
 - Long Material Lead Times
 - Cost & Schedule Prohibitive



Shaft 235 Repair: Plan




- Replace Poor Material With New Concrete
- Seal Out Groundwater And Soil With 8.2' OD Casing + Grout
- 4' Diameter Central Core To Gain Access To Regions



Shaft 235 Repair: Plan



- Final Demolition And Surface Preparation By Hand
- Inspection
- Concrete Replacement With Self-consolidating Mix
- Post-repair Evaluation



Shaft 235 Repair: Designer Responsibility




- Evaluate Stability At Each Stage
- Analysis Of Proposed Repair
- Verify Composite Behavior
- Impact Of Installing Casing (SWI)
 - To Existing Shaft
 - Performance Of Final Condition
- Inspections
- Final Analysis



Shaft 235 Repair: Execute

- Installing Casing and Coring




Shaft 235 Repair: Execute

- Installing Casing and Coring



Shaft 235 Repair: Execute


- Inspection



Shaft 235 Repair: Execute





- Inspection



Shaft 235 Repair: Execute

- Repair & Pour Back




Cement silo

Grout mixing tubs

Pump


Power Plant



Shaft 235 Repair: Recovery



- CSL Re-testing & Verification Coring
 - Damaged CSL Tubes




Cyl ID	Cast Date	Break Date	Age	Description	Frac Type	Test Load	Test PSI	Spec PSI
13494	10/27/15	11/24/15	28	Shaft 235 repair	3	102695	8170	6500
13495	10/27/15	11/24/15	28	Shaft 235 repair	3	103190	8210	6500
13496	10/27/15	11/24/15	28	Shaft 235 repair	3	96240	7660	6500


Shaft 235 Repair: Recovery



- As-built Analysis Via Fb-pier
 - Verify Force Distribution
 - Confirm Capacity





Typical Section Through 13.5'-Deep Anomalous Region




Shaft 235 Repair: Recovery



■ As-Built Analysis via FB-Pier



Shaft 235 Repair: Recovery




Conclusion

- Had Bad Concrete
- Developed And Vetted Solutions
- Implemented And Followed Quality Plans For The Repair
- Provided An End Product That Would Perform As Intended

Lessons Learned

- What Led To The Poor Concrete
- Teamwork Combined With Early And Often Engagement Is Mission Critical
- Don't Overlook The Straightforward Approaches



Special Thanks to Those Making It Possible



Applied Foundation Testing

■ HNTB

- San Jose, CA
- Oakland, CA
- Lake Mary, FL
- Kansas City, MO





Questions?

Contact Information: Alan Marchman, PE
HNTB Corporation
cmarchman@hntb.com

Kuan Go, PE, SE
HNTB Corporation
kgo@hntb.com