

# Clarence L. Gosse Memorial Bridge Rehabilitation

Christopher R. Dyck, M.Sc., P.Eng.  
Senior Bridge Specialist

**COWI**

Western Bridge Engineers Seminar, Phoenix AZ, December 5-8, 2023



# Agenda

- Project Elements and Team
- Bridge Description
- Project Goals
- History of Construction and Midspan Sag Development
- Preventative Maintenance
- Concrete Deck Assessment
- Concrete Deck Repairs
- Waterproofing Membrane Selection and Replacement
- Expansion Joint Replacements
- Midspan Joint Bearing Block Replacements
- Midspan Sag Assessment
- Questions

NORTH AMERICA



# Project Elements & Team

- **Design Management:** Nova Scotia Public Works (Chris Dyck, M.Sc. P.Eng.)
- **Construction Management:** Nova Scotia Public Works (Ray Daniels, P.Eng.)
- **Concrete Deck Assessment:** Wood (Chris Barnes, P.Eng., Ph.D.)
- **Tendon Assessment:** W.S. Langley Concrete (Wib Langley, P.Eng.)
- **Structural Design:** Harbourside Engineering Consultants (Wade Pottie, ing., P.Eng.)
- **Bridge Cleaning:** Balfour Property Restoration
- **Concrete Rehabilitation Contractor:** Wilcraft Concrete Services (Troy Grant, P.Eng.)
- **Licensed Membrane Installer:** Wilcraft Concrete Services (Troy Grant, P.Eng.)
- **Asphalt Contractor:** Miller Group under direction of Wilcraft

# Bridge Description



- Rt 236 over Shubenacadie River
- Tributary to Bay of Fundy
- Swift river currents
  - 6 to 12 ft/s
- Tide effects:
  - -1ft to +32ft
  - River width varies 300'-1400'
  - Ice flows on tide cycle
- Main span 700'
- Side Spans 372'
- Total length 1444'







# Bridge Description

- 32' driving surface with 2" Asphalt + Curb O/H
- Superstructure:
  - 20' Box girder width; 7'-5" Cantilever overhangs
  - 8' to 35' Box girder depth
  - 14" Webs; 10" to 13" Top slab; 6" to 5'-6" Bot Slab
  - 354 - 1 ¼" DYWIDAG bar tendons crossing pier table
  - 8 - 1 ¼" DYWIDAG bar tendons anchored midspan




# Bridge Description

- Substructure:
  - East Pier on Bedrock
  - Piled West Pier (182 H piles)
  - Piled Abutments (10 H piles)
  - 1" Steel/4" Concrete Ice Shielding on Piers



(14) CAST FINAL SECTION OF PIER & REMOVE FRAME 1 & SHEET PILES



WING WALL REINFORCING (2-SIMILAR) SECTION: A-A

# Project Goals

- Achieve Additional 40–50-year Service Life:
  - Improve Riding Surface
  - Clean the Bridge
  - Repair Concrete Deck, Curb, and Rail
  - Preserve the Concrete Deck Following Repair
  - Replace the Midspan Joint Bearings
  - Replace all Expansion Joints
  - Assess the Midspan Sag



# History of Construction and Midspan Sag Development

- Cast-in-place balanced free cantilever method
  - East pier/cantilevers completed in winter weather
  - West pier/cantilevers completed 9 months after East half finished
  - Longest span of this type in NA at the time
- Midspan Sag Development
  - Different concrete placement, curing environments
  - Delay and non-concurrent cantilever construction difficult to overcome
  - Challenging field construction through all weather
  - More difficult at that time to predict creep and shrinkage
  - 1978-2018: 2 ft midspan sag



# History of Construction and Midspan Sag Development



East Span – Note Icy Winter Conditions



West Span – Summer construction



# History of Construction and Midspan Sag Development

- South Side (Facing up-river)



October 27, 1978



November 28, 2018



# History of Construction and Midspan Sag Development

- North Side (Facing Bay of Fundy)



January 8, 1979



October 19, 2018



# Preventative Maintenance

- Vandalism resulted in serious bird infestation
- Heavy steel covers installed to prevent vandalism and bird damage







# Preventative Maintenance

- Deck drain reinstatements
- Extension below girder soffit




# Concrete Deck Assessment

- Copper Sulphate Electrode (CSE) potential testing
  - Active and transition potential maps
    - Total Active + Transition Area = 4000 Sq.ft.
    - Actual Repair Area of Deck = 3700 Sq.ft.







# Concrete Deck Assessment



PLAN  
1:650



LOOKING UP



A SECTION - NEW CSE POTENTIAL ROD  
RE1 1:8

### CSE POTENTIAL ROD NOTES:


1. BLAST CLEAN EXISTING STEEL TO COME IN CONTACT WITH NEW POTENTIAL RODS IN ACCORDANCE WITH DIVISION 5, SECTION 13 ON NSTIR STD. SPEC TO ENSURE PROPER CONDUCTION/ELECTRICAL CONTINUITY.
2. ELECTRICAL CONTINUITY MEASUREMENTS SHALL BE TAKEN BETWEEN GROUND ROD LOCATIONS AND SHALL NOT EXCEED 0.003 OHMS. ELECTRICAL CONTINUITY SHALL BE VERIFIED AND RECORDED BEFORE AND AFTER GROUT PLACEMENT.





# Concrete Deck Assessment

- Ground Penetrating Radar (GPR)
- Tendon Investigation





# Concrete Deck and Curb Repairs

- Chain sounding of entire deck by NSDPW and Contractor
  - 3700 Sq.ft. of main deck repaired = 8% of total deck area
  - 2000 Sq.ft. of curb repaired
- Special Mix Design
  - Small aggregate
  - Low shrinkage
  - Congestion
- Tendon Protection
  - Duct perforations & exposed tendons repaired with epoxy suitable for cold climate
  - 15lb Hammers
  - Extreme caution around all tendons

# Concrete Deck and Curb Repairs





# Concrete Deck and Curb Repairs





# Concrete Deck and Curb Repairs





# Waterproofing Membrane Selection and Replacement

- Crack bridging
- Chemical, abrasion and puncture resistance
- Repairable (interlayer adhesion)
- Matacryn Membrane Selected





# Waterproofing Membrane Selection and Replacement

- Matacryl CM primer applied directly to prepared concrete deck
- Quartz sand was broadcast into the wet primer





# Waterproofing Membrane Selection and Replacement

- Matacryn membrane applied in several coats to required thickness



# Waterproofing Membrane Selection and Replacement





# Waterproofing Membrane Selection and Replacement

- Matacryl HM Tack Coat Prior to Paving





# Waterproofing Membrane Selection and Replacement

- Wearing course over Matacryn membrane





# Expansion Joint Replacements

- Expansion Joint Replacements – Midspan joint assessment 2018-2019





# Expansion Joint Replacements


- Expansion Joint Replacements – removal of midspan joint April 2020





# Expansion Joint Replacements

- Expansion Joint Replacements – WABO Transflex 900 installed



# Expansion Joint Replacements







# Expansion Joint Replacements



# Midspan Joint Bearing Block Replacements

- Midspan sag created challenges for removal of the bearing blocks





# Midspan Joint Bearing Block Replacements

- Midspan Joint General Layout






# Midspan Joint Bearing Block Replacements






# Midspan Sag Assessment

- DYWIDAG consulted (original designer from 1970s)
- All sections of cantilevers structurally stable and in equilibrium



# Midspan Sag Assessment

- External PT considered to compensate for midspan sag





# Midspan Sag Assessment

- External PT considered to compensate for midspan sag
  - Sufficient doubt introduced when studying the available information from the Koror–Babelthuap Bridge collapse in 1996 in Palau (Western Pacific)



Source: The Structural Engineer, 6 June 2006

- Conclusion: Sag primarily service issue to be monitored for remaining bridge life

# Conclusion

- Improved the Riding Surface
- Cleaned the Bridge
- Repaired Concrete Deck, Curb, and Rail
- Preserved the Concrete Deck Following Repair
- Replaced the Midspan Joint Bearings
- Replaced all Expansion Joints
- Assessed the Midspan Sag
- Service Life Monitoring will be ongoing (40-50 year life extension)
  - Maintaining gates and screens
  - CSE testing to monitor potentials in the deck
  - Structural Inspections



# Questions?

[chdy@cowi.com](mailto:chdy@cowi.com)

