

# Asset Preservation: System-Wide and Structure Specific Bridge Asset Management Plans





*Presenters:*  
*Travis Butz, PE*  
*David Van Atta, PE*







Bridge management is a core bridge discipline that focuses on making informed and effective decisions on the operation, maintenance, preservation, replacement, and improvement of bridges within a bridge inventory.



# 2 Types of AMPs

## System-Wide:

- Many Structures
- High-level Planning

## Single Structure:

- In-depth study
- Detailed Assessment



## Common Characteristics:

- Inventory of Assets
- Condition Assessment
- Life-cycle costs

# System Wide AMPs:



## City of Delaware, Ohio

- Population 42,800
- 46 total structures
- 24 bridges, 22 culverts
- Data Collection & Field Review
- Projection of repairs and maintenance required for 75-year duration



## City of Goodyear, Arizona

- Population 101,700
- 132 total structures
- 30 bridges, 102 culverts
- Data Collection & Field Review
- Current repairs only





# Bridge Inventory:



Structure Type	Count
Steel beam / girder	14
Stone Arch Culvert	1
Con-Span	8
3-Sided Box	1
Concrete Slab	8
Concrete Box Culvert	10
Elliptical Concrete	1
Steel Truss	2
Corr. Metal Pipe	1



- 30 bridges, 102 culverts
- All concrete structures
- Many multi-span slab bridges and multi-cell culvert structures



# AMP Development:

Phase 1 – Data collection and Review

Phase 2 – Field Review

Phase 3 – Maintenance / Repair Plan


Phase 4 – Life Cycle Costs

Phase 5 – Deliverables  
(Plan Document / Data  
Updates / Website)

## BRIDGE MAINTENANCE AND REPLACEMENT PLAN

City of Delaware, Ohio

FINAL REPORT



CITY OF GOODYEAR

## BRIDGE REPAIR/REHAB PRIORITIZATION AND COST ESTIMATING REPORT

April 17, 2020


BURGESS & NIPLE



# Phase 1 – Data Collection and Review

## Data Sources:

- Existing plans
- As-built drawings
- City GIS info
- Existing Photos
- Inspection reports
- Load ratings
- Scour assessments
- Others...



**ARIZONA DEPARTMENT OF TRANSPORTATION**  
**BRIDGE GROUP**  
**Bridge Technical Section**

Expires on 09/30/2015

**Bridge Load Rating Summary Report**

---

**I. General Information**

Structure No. <b>7565</b>	Structure Name: <b>Gila River Bridge</b>	Rated By: <b>Mokarrom Hye, P.E.</b>
Route: <b>0</b>	Location: <b>0.80</b>	
Mile Post: <b>0</b>	Owner: <b>Good</b>	
District: <b>Phoenix</b>	Year Built: <b>1987</b>	
County: <b>Maricopa</b>	Year of Reconst.: <b>NA</b>	

**ARIZONA DEPARTMENT OF TRANSPORTATION**  
**BRIDGE GROUP**  
 Structure Inventory and Appraisal

Structure Number : **07565**    Structure Name : **Gila River Bridge**    Feature Under : **Gila River**  
 Route : **0**    MP : **0**    Road Name : **Estrella Parkway**    Agency: **Goodyear**    Location : **0.8 mi S of Broadway**

LOCATION INFORMATION		DIMENSIONS		PROPOSED IMPROVEMENTS	
N1-State Code :	049	N32-Appr Rdwy Width (feet):	36	N75-Type of Work:	
N2-State Hwy District :	Central	N48-Max Span Length (feet):	121	N76-Length of Str Imp (feet):	0
N3-County Code :	013	N49-Structure Length (feet):	2175	N94-Br Improv Cost (x1000):	\$0
N4-Place Code :	28380	N50a-Lt Curb/Swlk Width (feet):	0.0	N95-Rdwy Improv Cost (x1000):	\$0
N16-Latitude:	33 Deg 23 Min 18.24 Sec	N50b-Rt Curb/Swlk Width (feet):	4.0	N96-Total Project Cost (x1000):	\$0
N17-Longitude :	112 Deg 23 Min 32.64 Sec	N51-Br Width Curb-Curb (feet):	36.0	N97-Year of Cost Estimate:	
N98-Border St Code - % Resp:		N52-Deck Width Out-Out (feet):	44.0		
N99-Border Bridge Number:		N112-NBIS Br Length?	Y		
INVENTORY ROUTE DATA		VERTICAL & HORIZONTAL CLEARANCE		CONSTRUCTION PROJECT DATA	
N19-Detour Length (miles):	4	N53-Min Vert Over Clr (feet):	99.99	N106-Year of Reconstruction:	1988
N20-Toll:	3	N54-Min Vert Under Clr (feet):	N 0.00	A204-Orig Project Number:	4721-06
ROADWAY RECORD    ON    UNDER		N55-Min Lat Under Clr Rt (feet):	N 0.0	A205-Orig Project Station:	9+97.25
N5-Inv Rte:	1 5 0 00000 0   -	N56-Min Lat Under Clr Lt (feet):	0.0	A223-TRACS Number:	
N28-Lanes:	2    0	SERVICE TYPE and SPAN INFORMATION		A225-Deck Area (sq. feet):	95700



# Phase 2 – Field Review

- 2-person team
- Verify information obtained in data collection phase (condition ratings / repair recommendations)
- Fill gaps in collected data
- Collect repair quantity data to support cost estimating





# Phase 3 – Maintenance / Repair Plan

- Record created for each structure
- Includes collected data for each bridge (structure type, age, dimensions, condition factors, etc.)
- Recommendations for maintenance and repairs includes dates, frequency, and associated costs

**CITY OF DELAWARE, OHIO BRIDGE MAINTENANCE AND REPLACEMENT PLAN**  
SFN: 2101505 Sr 37 over Delaware Run




Structure Number: **2101505**  
 Facility Carried: **Sr 37**  
 Feature Intersected: **Delaware Run**  
 Location: **0.08M**  
 Date Built: **7/1/1955**  
 Major Reconstruction Date: **N/A**  
 Total Spans: **1**  
 Overall Length: **30 Ft**  
 Superstructure: **Concrete**  
 Rear Abutment: **Concrete**  
 Forward Abutment: **Concrete**  
 Piers: **N/A**  
 Wearing Surface: **Bituminous**  
 Thickness: **5.4 in**  
 Date of Wearing Surface: **9/17/2019**

## STRUCTURE ASSESSMENT

Current Age: **68 years (Built in 1955)**      Immediate Action Required?: **NO**  
 Estimated Remaining Life: **5 years**      Total City Responsible Repair/Maintenance Costs: **\$0**  
 End of Structure Life (Estimated Year\*): **2028**      Recommended Inspection Frequency: **24 months**  
 \*Current Age + Estimated Remaining Life from 2022 Field Visit Assessment

**The structure is in good condition. The City should power wash the bridge once a year (preferably in the spring after the last deicing), and continue to monitor the structure for spalls in the structural concrete and the condition of the railing.**

Annual (Minor) Maintenance Costs	
Work Performed	Estimated Cost
Bridge Washing/Deck Sweeping	\$500 <i>includes cleaning debris from deck</i>

### Supporting Calculations


**Site Visit Note:** Seal cracks in wearing surface and approach. Cracks have previously been sealed and newer cracks need sealing.  
 Assume this is done with general roadway work.

**Site Visit Note:** Pipe conduit on north edge has breaks/corrosion and needs replaced. Wire conduit on north edge is not encased. Rubber shedding is starting to fray exposing wires inside.  
 Assume \$500

**Site Visit Note:** Fascia curb is cracked along N face 15' at bottom line of railing bolts. Interface between slab and fascia curb is spalling on the slab side with exposed rebar. Similar but less severe on south edge. 5' crack along south fascia.  
 Major Maintenance - Responsibility of ODOT

# Phase 4 – Life Cycle Costs

- 75-year projection
- Includes maintenance, rehabilitation, and replacement costs
- Projects anticipated yearly expenditures





# Phase 5 – Deliverables

- Provided Delaware with a written report along with electronic data
- Delaware will add data to online management system
- Integrated data into Goodyear's Lucity Asset Management System
- Incorporated into ArcGIS Online and Field Maps Application

## BRIDGE MAINTENANCE AND REPLACEMENT PLAN

City of Delaware, Ohio

## FINAL REPORT







OBJECTID	169
NBI Structure ID	
Unique Structure ID	SDC-05197
Structure Name	Box Culvert
Jurisdiction	SDC
Structure Type	Culvert - Concrete
Inspection Frequency	48
Inspection Frequency Units	Months
Facility Carried	W Willie Rd
Feature Intersected	Drainage ditch
Location	Just north of S 181st Ave
Latitude	33.304505
Longitude	-112.437244
Year Built	
Structure Width	1.500000

City of Goodyear Inspection			
148 records, 1 selected			
	NBI Structure ID	Unique Structure ID	Structure Name
	7565	7565	Estrella Parkway
	7566	7566	Bullard Road

# Data Application

- Assembled data provides the cities with a tool to help schedule maintenance, prioritize repairs, and plan for future capital expenditures
- Electronic systems allow for condition updates and the addition of new structures





# I. B. Perrine Bridge




- Twin Falls, ID
- Snake River Canyon
- Opened 1976
- 1500 ft long
- 993 ft main span
- 486 ft high



# ITD Bridge Asset Management Plans

- ITD developed eight individual Bridge Asset Management Plans for high-cost replacement bridges
- AMPs are used to analyze future funding scenarios and tradeoffs to ultimately pay for replacing these structures
- Data from AMP is used to perform life cycle cost analysis in BrM
- BrM accounts for the effect of rehabilitation project on condition of bridge components



Element	Str. Unit	Env.	Quantity	Units	Starting Conditions	Effect
(12) Re Concrete Deck	0	Sev.(4)	117750	sq.ft		
(107) Steel Opn Girder/Beam	0	Low(2)	2014	ft		
(113) Steel Stringer	0	Low(2)	8397	ft		



Data Sufficiency  
Memorandum

Bridge Condition  
Assessment

Risk Register

Asset Management Plan

Alternatives  
Analysis Matrix

Maintenance and  
Monitoring Manual

# Data Sufficiency Memorandum

- Compile & review existing documents:
  - Plans, shop drawings, load ratings, inspection reports
- Tabulate key information

Date	Event
1972	Original Design Plans Submitted
1976	I.B. Perrine Bridge opened to traffic
1994	<b>Rehabilitation</b> -Abutment Expansion Joint Repair -Deck Modifications -Parapet Modifications -Replace Finger Joints with Modular Expansion Joints -Fill Top Quadrants of Skewback Castings with Elastomeric Concrete -Install Pest Screens and Access Hatches -Drill Out Cracks in Girders -Median Light Supports
2008	<b>Rehabilitation</b> -Replace Modular Joint Control Springs -Replace Modular Joint Nylon Dowels -Replacing Missing or Loose Bolts. -Install Utility Conduits

ASTM A514 STEEL ELEMENTS				
File	Page	Welded	Description	Note
001 (JPG)_1973ShopDwgs1-112	14/112	Yes	L10-L12	L10'-L12' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	14/112		L11 Splice Plates	L11' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	14/112	Yes	L12 Gusset Plate	L12' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	14/112	Yes	L12 Gusset Plate Edge Stiffeners (welded to gusset plate)	L12' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	16/112	Yes	L12-L14	L12'-L14' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	16/112		L13 Splice Plates	L13' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	16/112		L13 Lower Lateral Gusset Plate	L13' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	16/112	Yes	L14 Gusset Plate	L14' assumed to be similar
001 (JPG)_1973ShopDwgs1-112	16/112	Yes	L14 Gusset Plate Edge Stiffeners (welded to gusset plate)	L14' assumed to be similar



# Bridge Condition Assessment

- Selective visual inspection
- Chloride concentration sampling (deck and abutments)



Location	Depth	Low Contamination	Moderate Contamination	Advanced Contamination	Avg. Concentration (lb/cy)
Deck	1"	88%	13%	0%	0.60
	2.5"	100%	0%	0%	0.14
North Abutment	1"	67%	0%	33%	1.27
	2.5"	67%	33%	0%	0.58
South Abutment	1"	67%	0%	33%	0.93
	2.5"	100%	0%	0%	0.04

# Risk Register

- Workshop with Key Stakeholders
- Identify risks and opportunities
- Quantify likelihood of occurrence
- Identify mitigation options, estimate cost



Risk ID	Risk Name	Risk Descriptions
Risk 1	<b>Gusset Plate Edge Stiffener Welds (A514)</b> Probability: 200 years (0.5%); Consequence Score: 16; Risk Ranking: 29/30; Risk Type: Asset	Several elements on the bridge are comprised of A514 Steel. Included in this are many of the gusset plate edge stiffeners. Steel elements can be prone to cracking when welded and in tension. Bridge inspections identified and repaired the gusset plate edge stiffeners – photographs were shown during the risk workshop. Crack repairs. The workshop survey of potential financial impacts achieved consensus on low financial impacts (11% estimated very low impacts) – roughly \$1M expected to arrest cracks and retrofit welded edge stiffeners.
Risk 2	<b>Significant Isolated Fatigue Cracks in Steel</b> Probability: Every 20 years; Consequence Score: 7.5; Risk Ranking: 20/30; Risk Type: Asset	Increases in loading cycles (volume and number of trucks) and environmental corrosion leads to localized fatigue cracking. The risk of failure is very low, partial closures would be necessary for repair, and financial consequences are estimated to be low.



# Alternatives Analysis Matrix

- Identify alternatives for maintenance and rehabilitation actions
- Determine future cost outlays for each alternative
- Present alternatives in a Decision Matrix
- Develop bridge replacement alternative

<b>Bridge Element</b> Known deficiency	<b>Recommended Rehabilitation</b>	<b>Cost Estimate</b> (2020 Dollars)
<b>Deck: Joints</b> Sliding plates at sidewalk joints require repair/replacement.	Repair Sidewalk Joints, Future Repair and Replacement of Modular Joints at ends of Arch Span, Future Replacement of Compression Seal Joints at Abutments.	\$804,000
<b>Deck: Wearing Surface</b>	Future Polyester Overlays and Friction Treatments	\$4,876,000
<b>Deck: Sidewalks, Parapets and Barrier</b>	Seal Sidewalks, Parapets and Barriers, Future Replacement of Pedestrian Railing	\$1,432,000

# Alternatives Analysis Matrix

## Partial Decision Matrix:

Rehabilitation Actions													Service Life 2020 – 2075	
	ITEM	YEAR											TOTAL COST ESTIMATE	
		2022	2025	2030	2035	2040	2045	2050	2055	2060	2065	2070		2075
DECK ALTERNATIVE 1 (MAINTAIN EXISTING DECK)	Repair Sidewalk Joints	\$18,000					\$18,000							\$36,000
	Repair Modular Joints			\$160,000						\$160,000				\$320,000
	Replace Modular Joints						\$400,000							\$400,000
	Replace Abutments Joints			\$16,000			\$16,000			\$16,000				\$48,000
	Apply Polyester Overlay				\$2,156,000					\$2,156,000				\$4,312,000
	Friction Treatment		\$188,000				\$188,000					\$188,000		\$564,000
	Seal Sidewalks, Parapets and Barrier (Silane)				\$81,000				\$81,000					\$162,000
	Seal Sidewalk Cracks (HMWM)		\$37,000	\$37,000	\$37,000	\$37,000	\$37,000	\$37,000	\$37,000	\$37,000	\$37,000	\$37,000	\$37,000	\$370,000
	Remove and Replace Pedestrian Railings			\$900,000										\$900,000
	Repair Soffit Spalls	\$15,000				\$15,000				\$15,000				\$45,000
<b>Deck Alternative 1 Total:</b>	<b>\$33,000</b>	<b>\$225,000</b>	<b>\$1,113,000</b>	<b>\$2,274,000</b>	<b>\$52,000</b>	<b>\$659,000</b>	<b>\$37,000</b>	<b>\$118,000</b>	<b>\$2,384,000</b>	<b>\$37,000</b>	<b>\$225,000</b>	<b>\$0</b>	<b>\$7,157,000</b>	
DECK ALTERNATIVE 2 (DECK REPLACEMENT)	Repair Sidewalk Joints	\$18,000												\$18,000
	Repair Modular Joints			\$160,000						\$160,000				\$320,000
	Replace Abutment Joints									\$16,000				\$16,000
	Apply Epoxy Overlay									\$281,000				\$281,000
	Friction Treatment		\$188,000					\$188,000				\$188,000		\$564,000
	Seal Sidewalks, Parapets and Barrier (Silane)									\$81,000				\$81,000
	Remove and Replace Deck, Sidewalks, Joints, Parapets, Barrier, and Pedestrian Railings						\$11,863,000							\$11,863,000
	<b>Deck Alternative 2 Total:</b>	<b>\$18,000</b>	<b>\$188,000</b>	<b>\$160,000</b>	<b>\$0</b>	<b>\$11,863,000</b>	<b>\$0</b>	<b>\$188,000</b>	<b>\$0</b>	<b>\$538,000</b>	<b>\$0</b>	<b>\$188,000</b>	<b>\$0</b>	<b>\$13,143,000</b>

# Maintenance and Monitoring Manual

- Identify critical areas for inspection and monitoring
- Recommended schedules for inspection and maintenance
- Report includes a Maintenance Log to note changing conditions and repairs

**Access: From an Underbridge Inspection Vehicle**



**Monitor**

Stay-In-Place Forms: Inspect and monitor the metal stay-in-place forms for corrosion and other signs of leaking. This is indicative of water infiltration through the deck slab and/or access hole penetrations which accelerates deterioration of the deck, forms and superstructure components below.




**Corrosion on SIP Forms**

Deck slab	12	Bi-annual, as part of NBI inspection	From underbridge inspection vehicle	Inspect metal stay-in-place deck forms for corrosion and leaking
General Notes				
Required Additional Repairs				




# Asset Management Plan

- Provides an executive summary of the content of the component reports
- Rehabilitation, maintenance, and replacement recommendations
- The five component reports are included as appendices




# Repair Project

- Repairs to arch end posts
- Painting of corrosion-prone areas
- Inspection access system repairs
- Patching of concrete substructures
- Utility conduit repairs
- Sidewalk joint repairs
- Railing repairs






# Repair Project - End Posts






# Repair Project - End Posts



# Repair Project - End Posts



**CLEMCO®**

## Pipe Tools

### INTERNAL PIPE BLASTING

Precise, Efficient, Economical

**CLEMCO®** | **MADE IN THE USA**

## SPIN-KOTE

### INTERNAL PIPE COATING EQUIPMENT

***IMPORTANT:** For safe, efficient blasting, read and follow the owner's manual and seek training for everyone who will use this equipment.*

**OPERATION:**  
Paint is applied in a 360-degree pattern by the centrifugal force of the spinning spray head. The coating material is fed to the spray head through a fluid manifold for maximum, even, distribution. The volume of coating material is adjusted by changing the pressure on the paint pump or by changing the media orifice used in the back-pressure assembly. Coating thickness is controlled by the speed at which the Spin-Kote is moved through the pipe.

**APPLICATIONS:**  
The Spin-Kote can be used with any coating that can be applied with an airless spray system. Typically, pipes are coated internally for potable water.

**Spin-Kote 1236**  
Stock No. 27023

for pipe 12" to 36" ID





Thanks!

**B&N**  
burgessniple.com

