A 3D finite element model of a concrete arch bridge, rendered in a light blue color. The model shows the bridge's structure, including the arches, piers, and deck. Small green dots are placed at various points along the bridge, likely representing nodes or sensors for seismic evaluation. The bridge is shown from an elevated perspective, highlighting its curved arches and the supporting piers.

Seismic Evaluation of a Historic Concrete Arch Bridge.


Depoe Bay Bridge

Sean White P.E.

Oregon DOT

A little historical background:

- Coastal communities accessed by highways from the Willamette Valley or the Sea.
- In 1913 the entire Oregon beach established as a public highway.
- Although the Oregon coast highway (Roosevelt Highway) was envisioned, it was not largely developed.
- A 1918 trip from Marshfield (Coos Bay) to Crescent City took over 50 hours.



ODOT Map Adapted from Book "Lifting Oregon Out of the Mud"

The mail must get through!

The Mail must get through, circa 1915 #598T
These brave and persistent mailcarriers from the past race the surging tide to make their appointed rounds. Up until the early 1930's the road systems along the Oregon Coast consisted of Indian trails and a few very muddy roads. So the vast stretches of sandy beach along the Oregon Coast served as roads for all manner of transportation north and south.

Copies available -
P.O. Box 161
Newport, OR 97365
(541) 867-3430
www.forinashgallery.com




MADE IN
USA
MAR46412-15b



US Mail Stage at High Tide on the Oregon Coast, circa 1915

The original Depoe Bay bridge was designed in 1926, built in 1927.



One of the early Conde McCullough bridges.

1927 biennial report on the original construction.

Depoe Bay Bridge

Federal Aid Project No. 110C


On the Roosevelt Coast Highway, 4.07 miles north of Otter Crest and 13.9 miles north of Newport; one 160-foot concrete arch span and 150 feet of concrete viaduct approach.

Contract 888, awarded May 25, 1926, to Kuckenbergh-Wittman Co., of Portland, Oregon. Work commenced July 13. Estimated cost, \$54,000, to be paid \$21,577.50 from state funds and \$32,422.50 from government funds. Expenditures to date, \$38,023.38 from state funds. Resident Engineer, J. T. Skelton.


Excellent progress has been made on the construction of this structure and the work is now about 85 per cent complete. At the time of awarding the contract no acceptable sources of local sand had been found and it was expected that this material would have to be shipped in from the Willamette Valley. However, an excellent deposit of sand has been discovered on the beach, and the immediate availability of the material has contributed favorably to the progress of the work. Rock for the concrete is being secured from a quarry alongside the highway at a point about 2 miles south of the bridge site.

1927 Bridge

- Original bridge had two 10-foot travel lanes and no sidewalks.



Photograph and Postcard of the early bridge.




The world's smallest navigable harbor.

Some is good, more is better!

- After the major river crossings were built during the Depression, the need for more capacity was clear. Yaquina Bay bridge (Newport) was completed in 1936.
- Widening designed for Depoe Bay Bridge in 1939, built in 1940.
- Widening structure was twice the width of the original, 20-foot roadway became 50-foot, plus two 5-foot sidewalks, for a total of 60 feet.
- The widening is a separate structure. The two are adjacent but not attached.
- McCullough had left the State Bridge Engineer's position in 1936, but his influence is clear.

1940 widened bridge. BR # 2459



1940 biennial report on the widening construction

REPORT OF BRIDGE DEPARTMENT

G. S. PAXSON, *Bridge Engineer*

Depoe Bay Bridge Widening: Depoe Bay is one of the most interesting and spectacular spots on the Oregon Coast High-

way. The Spouting Horns and the narrow inlet to the bay attract thousands of spectators each year. The original structure over the inlet was built in 1926 and had an 18-foot roadway with no sidewalks. People would congregate on the bridge to watch fishing boats enter the inlet to the bay. This created an extreme traffic hazard, both to the spectators on the bridge and to the vehicular traffic crossing the structure. To correct this condition, the original structure was widened by the construction of new arches and a roadway alongside the existing structure to give a 48-foot roadway and two 5-foot sidewalks. A walkway under the north end of the structure makes it possible for pedestrians to cross from the business section on the east side of the highway to the State park on the west side of the highway without danger. This is only one unit of the contemplated improvement at this site. The entire improvement, when completed, will include widening of the roadway in the vicinity of the site and the provision of parking areas for sightseers.

The contract for the bridge construction was awarded on December 8, 1939, to the Odom Construction Company of Oregon City, Oregon. Construction was completed on November 15, 1940, at a cost of \$60,367.

Depoe Bay Bridge today (Google Maps).

Channel House
jimi mckillip jr
Sep 2022



Sep 2022

View from the water.



A pretty little Bridge.

The need for seismic evaluation.

- The primary work on this bridge is to update of the Cathodic Protection system and repair the bridge railing.
- The need to replace existing seismic restrainers provided an opportunity to revisit the design.
- The scope of the seismic work is limited to Phase 1 life safety retrofit.



Figure 1: Example of corroded seismic restraint cables.




Figure 2: Example of corroded nuts and anchors

Life Safety Criteria.



Project Name:	Depoe Bay	Key Number:	20110
Highway:	OREGON COAST HWY. NO. 9 (US26, US101)	Milepost:	127.61
Structure:	Depoe Bay, Hwy 9	Structure No.	02459, 01138
County:	Lincoln		
Designer:	Sean White		

Saturday, August 19, 2023

Project Type

Existing Bridge - Seismic Retrofit

Latitude (Deg) Longitude (Deg)

44.8097 -124.0619

(42°00' to 46°18') (-116°27' to -124°34')


EQ Return Period

1000 Years ~ (Life Safety Criteria)

2014 USGS Seismic Hazard Data

Site Class	PGA (g)	S _s (g)	S ₁ (g)	F _{pga}	F _a	F _v	A _s (F _{pga} *PGA)	S _{DS} (F _a *S _s)	S _{D1} (F _v *S ₁)	SDC
A	0.5014	1.0497	0.4186	0.8000	0.8000	0.8000	0.4012	0.8398	0.3349	III

Period, T (sec)	S _a (g)
0.00	0.3359
0.08	0.8398
0.20	0.8398
0.40	0.8398
0.40	0.8373
0.60	0.5582
0.80	0.4186
1.00	0.3349
1.20	0.2791
1.40	0.2392
1.60	0.2093
1.80	0.1861
2.00	0.1675
2.20	0.1522
2.40	0.1395
2.60	0.1288
2.80	0.1196
3.00	0.1116
3.20	0.1047
3.40	0.0985
3.60	0.0930
3.80	0.0881
4.00	0.0837



ODOT_ARS_V2014.20

Building the model.

Coordination:

Control lines parallel but running in different directions.

Two different elevation datum.

The screenshot shows an Excel spreadsheet with a green ribbon and a data table. The table has columns labeled A through T. A key in the top right corner identifies the colors used in the table: Not used (white), BR1138 (green), BR2459 (orange), and Varified adjusted (yellow). The spreadsheet shows data for various features like 'Feature BR1138', 'North edge, BR1138', 'Pier 2 BR1138', and 'Spandral Column 9, BR1138'.

Stationing BR1138	(Dwg. 3343)	Deck elev	Ftg elev	Top ftg	Top of col	Offsets(old)	Stationing BR2559	(Dwg. 6865)	Deck elev	Offset(new)	Adj Ftg elev	Adj top ftg	Adj top col	elv D&G Bk	elv D&G Ah	elv x-bm Bk	elv x-bm Ah	Key
Feature BR1138							Feature BR2459	386+95.58										Not used
							N. deck edge BR2459	386+96.83	56.95									BR1138
							Bent 0	387+15.00	57.08									BR2459
North edge, BR1138	215+47.00						Bent 1	387+16.25	57.08	-9	48.00	49.53	54.50		56.30			Varified adjusted
Bent 4	215+46.00	61.17	51.87	53.62	58.59	7.50		387+16.25	57.08									
Pier 2 BR1138	215+25.00	61.41		24.50	57.41	8.00	BR2459 E.Pier1	387+45.25	57.56	5	0.00	21.00	53.06	56.54	56.82	55.32	55.32	
							BR2459 W.Pier1	387+58.29	57.70	-23	-3.00	21.00	53.20			55.45	55.70	
Spandral Column 10, BR1138	215+08.69	61.55		37.14	56.80	8.00		387+53.56	57.46		21.69	33.05	52.96	56.96		56.09		
Spandral Column 9, BR1138	214+95.65	61.66		46.76	56.91	8.00		387+66.60	57.57		32.03	42.67	53.07	57.07		56.20		
Spandral Column 8, BR1138	214+82.60	61.77		53.22	57.02	8.00		387+79.65	57.68		47.00	49.13	53.18	57.18		56.31		
Spandral Column 7, BR1138	214+69.56	61.88		57.13	57.13	8.00		387+92.69	57.79		51.65	53.04	53.29	57.29		56.42		
Spandral Column 6, BR1138	214+56.52	61.99		59.49	59.49	8.00		388+05.73	57.90		53.87	55.40	53.40	57.40		56.65	55.90	
Spandral Column 5, BR1138	214+43.48	62.10		59.60	59.60	8.00		388+18.77	58.01		53.87	55.51	53.51		57.51	56.01	56.76	
Spandral Column 4, BR1138	214+30.44	62.21		57.46	57.46	8.00		388+31.81	58.12		51.65	53.37	53.62	57.62		56.75		
Spandral Column 3, BR1138	214+17.40	62.32		53.77	57.57	8.00		388+44.85	58.23		47.00	49.68	53.73	57.73		56.86		
Spandral Column 2, BR1138	214+04.35	62.43		47.53	57.68	8.00		388+57.90	58.34		32.03	43.44	53.84	57.84		56.97		
Spandral Column 1, BR1138	213+91.31	62.54		38.13	57.79	8.00		388+70.94	58.45		21.69	34.04	53.95	57.95		57.08		
Pier 1 BR1138	213+75.00	62.70		24.50	58.70	8.00		388+87.25	58.61		12.00	20.41	54.11	58.11	57.26	56.61	56.24	
							BR2459 E.Pier2	388+95.25	58.77	5	3.00	21.00	54.27			56.77	55.56	
							BR2459 W.Pier2	389+08.29	58.82	-23	-4.00	21.00	54.32		58.38	55.61		
Bent 3, BR1138	213+30.69	62.87	20.00	22.00	52.29	7.50		389+31.56	58.78		15.91	17.91	48.20	57.43		52.36		
Bent 2, BR1138	212+89.69	62.95	46.00	48.00	56.70	7.50		389+72.56	58.86		41.91	43.91	52.61	57.51		56.49		
Bent 1, BR1138	212+48.69	62.95	51.00	53.00	56.20	7.50		390+13.56	58.86		46.91	48.91	52.11	57.51		56.49		
South edge, BR1138	21247.94							390+14.31										
							E Spandral Column A	387+61.56	57.74	5	29.11	33.88	51.74	57.3		55.74		
							E Spandral Column B	387+74.60	57.88	5	39.45	43.33	51.88	57.44		55.88		
							W Spandral Column B	387+74.60	57.88	-23	29.11	34.02	51.88	57.44		55.88		
							E Spandral Column C	387+87.65	58.01	5	47.00	50.07	52.01	57.57		56.01		
							W Spandral Column C	387+87.65	58.01	-23	39.45	43.46	52.01	57.57		56.01		
							E Spandral Column D	388+00.69	58.13	5	51.65	53.24	53.24	57.69		54.88		
							W Spandral Column D	388+00.69	58.13	-23	47.00	50.19	50.19	57.69		54.88		
							E Spandral Column E	388+13.73	58.24	5	53.87					56.24		
							W Spandral Column E	388+13.73	58.24	-23	51.65					56.24		
							E Spandral Column F	388+26.77	58.34	5	53.87					56.34		
							W Spandral Column F	388+26.77	58.34	-23	53.87					56.34		
							E Spandral Column G	388+39.81	58.44	5	51.65					56.44		
							W Spandral Column G	388+39.81	58.44	-23	53.87					56.44		
							E Spandral Column H	388+52.85	58.53	5	47.00	50.59	50.59	58.09	58.09	55.28		
							W Spandral Column H	388+52.85	58.53	-23	51.65	53.64	53.64	58.09	58.09	55.28		
							E Spandral Column I	388+65.90	58.61	5	39.45	44.06	52.61	58.17		56.61		
							W Spandral Column I	388+65.90	58.61	-23	47.00	50.67	52.61	58.17		56.61		
							E Spandral Column J	388+78.94	58.65	5	29.11	34.79	52.65	58.21		56.65		
							W Spandral Column J	388+78.94	58.65	-23	39.45	44.10	52.65	58.21		56.65		
							W Spandral Column K	388+91.98	58.69	-23	29.11	34.83	52.69	58.25		56.69		
							Bent 2 E.	389+35.25	58.91	5	10.50	12	48.16			54.91		
							Bent 2 W.	389+48.29	58.94	-23	7.50	9	48.19			54.94		
							Bent 3 E.	389+75.25	58.98	5	37.00	38.5	48.23			54.98		
							Bent 3 W.	389+88.29	58.99	-23	26.50	28	48.24			54.99		
							Bent 4 E.	390+15.25	58.98	5	38.00	39.5	51.81			55.40		
							Bent 4 W.	390+28.29	58.97	-23	38.00	39.5	51.80			55.39		
							Bent 5 E.	390+28.58	58.97	5	52.00	53	58.01					
							Bent 5 W.	390+41.62	58.95	-23	52.00	53	57.99	57.99				


Starting simple:

Simple block elements between control points.

Beam end releases to model joints.


Ridged links to tie sections together.

Section properties overwritten with hand calculated values.




Refining the model:

Adding arch ribs. Entered complex shapes which allowed software to calculate the section properties. Modified concrete stiffness to cracked section properties.






Watching it move.


About 3.5" lateral movement at the Pier Column to Spandrel Column supported deck joint.




Concrete Hinge (unreinforced concrete pedestal).




Adding complexity:




Looking at displacement at the restrainers.



Isolating the widening structure.




Tying the two together.



As long as we are here...

Take a look at the displacement demand on the lightly reinforced columns.

Full scale tests give data to compare to.



Full scale laboratory research of similar details.

SEISMIC PERFORMANCE DESIGN CRITERIA FOR BRIDGE BENT PLASTIC HINGE REGIONS

Final Report

SPR 802



Oregon Department of Transportation




Figure 4.2: (a) Column-footing longitudinal section details (b) Column cross sectional details (Section A-A), (c) Tie bar details, (d) Foundation cross section details

4.4 MATERIAL PROPERTIES

The specimens were built using a normal weight normal strength concrete and Grade 60 deformed steel bars. The specification for the material properties as obtained from the available bridge drawings were 'Class A' concrete mix with intermediate Grade 40 steel reinforcing bars.

Figure 6.7 shows the lateral load vs. displacement response of the tested RC square column and Table 6.5 lists material values for specific performance parameters.




Figure 6.7: Circular RC column performance. (a) Force-displacement hysteresis curve and (b) force-displacement envelope [Dusicka & Lopez (2016)]

Table 6.5: Bridge Performance Parameters (Limit States) for Circular RC Columns [Dusicka & Lopez (2016)]

Level	Limit State	Steel Strains (ϵ_s)	Concrete strains* (ϵ_c)	% Drift	Ductility (μ)
I	Cracking	0.0002	0.0004	0.20	0.3
II	First Yield	0.0013	0.0008	0.68	1.0
III	Effective Yield	-	-	-	-
IV	Onset of Spalling	0.0117	0.0046	2.55	3.8
V	Buckling Rupture	0.0402	0.0099	4.08	6.0

* The extreme concrete compressive strains of the columns were obtained using the results from the strains in the reinforcing steel and a linear strain profile for a circular section. The actual values of concrete strain in the confined section are expected to be lower since these values are the maximum compressive strain and not the strain in the confined section.

6.3.4 Square RC Column Tests (This Research) (4 - #8 Rebar)

The current experimental program investigated the seismic performance of square RC column-footing sub-assemblies consisting of three test specimens as illustrated in Figure 4.2. All three specimens had the same material properties, cross-sectional dimensions, and reinforcement ratios. The variables in the testing program include lateral and axial loading protocols. The longitudinal reinforcement in each prototype column consisted of 4 - #8 rebar in four corners. These were combined with #3 stirrups with 90° hooks, at 12 inches center-to-center spacing, and

Conclusions:

- The existing restrainers are unneeded as the movement demand at the joint is less than the capacity of the beam seats. Deleting the restrainers simplifies the Cathodic Protection system.
- Tying the two structures together will reduce the predicted lateral deck displacement, but not enough to affect the results.
- The concrete hinges will be damaged by the deck displacement but are unlikely to fail to support the span. If span drops enough to block traffic the widening structure can accommodate.
- Based on 'drift' alone, it is likely that the columns will survive the design earthquake.

Questions?

