

DAVID EVANS AND ASSOCIATES INC.

Executing a Major Urban Bridge Inspection

A Case Study on the West Marquam and East Fremont Interchanges

Makenzie Ellett, PE – Bridge Engineer & Inspector Matt Harlan, PE – Bridge Inspection & Preservation Group Leader



What makes a major bridge inspection different?



Local Agency Bridge



West Marquam Interchange



<u>08591A</u> Length = 1,940ft 17 Spans

<u>08591B</u> Length = 1,610ft 15 Spans

<u>08591C</u> Length = 1,900ft 15 Spans

<u>08591D</u> Length = 1,750ft 15 Spans

<u>08591F</u> Length = 1,140ft 14 Spans

East Fremont Interchange

- 08958 Length = 655ft 3 Spans Double-Decker
- <u>08958B</u> Length = 709ft 4 Spans Double-Decker

08958D Length = 1,580ft 12 Spans

<u>08958E</u> Length = 2,460ft 17 Spans

<u>08958F</u> Length = 1,030ft 8 Spans

<u>08958G</u> Length = 782ft 6 Spans

<u>08958H</u> Length = 1,040ft 6 Spans

<u>089581</u> Length = 1,040ft 7 Spans



Large Scale Inspections

- You are no longer trying to get 8-10 bridges done in a day... you are lucky to finish one
- Notes and photos must be very specific with Type, Size, and Location of defects
- You must be able to orient yourself at any point during the inspection
 - Bridge #, Span #, Girder #, North?, South?



Different Elements

Local Agencies


- Timber
- Concrete
 - Steel



Major Bridge

- Steel
- Steel

Steel



Steel Caps



Pin & Hanger Assemblies







Steel Box Girders



Non-Redundant Steel Tension Members

- Three Requirements:
 - No Load Path Redundancy
 - Steel Elements
 - In Tension
 - FKA "fracture critical" members
- "Failure would probably cause a portion of or the entire bridge to collapse."







Fatigue Prone

- Poor steel details combined with high number of stress cycles (truck loads)
 - Welded and coped steel members
 - Field welds
 - Intersecting welds
 - Short, welded attachments



Steel Cracks



Crack in the top of a longitudinal stiffener

Crack in the toe of a longitudinal stiffener

Crack in the toe of cross-bracing



Steel Crack Repairs



Crack Arrest Hole



Ground Out Crack



Weld Replaced with Bolts



Steel Cracks

DO NOT GET COMPLACENT!

- Do NOT blindly trust the previous report
- When in doubt, note it
- If you have a question, ask it
- Even repairs can fail





Coordination














Coordination with TriMet



Traffic Control

- Traffic control is one of the most important coordination items
- Engage your traffic control team EARLY and OFTEN
- Be willing to adapt
- Have an open line of communication during the inspection






Traffic Control



• Lane Closures vs Full Closures






Traffic Control





Teaming









Teaming

- Variety of new and experienced inspectors
- Orientation meetings before each night of work
 - Where? What? Who? When? How?
- ASK QUESTIONS



Equipment & Training








Reporting

39-Prestressed Slab SU 1 ENV 3 Gan not inspect Span 2 superstructure from banks
Edge spalls on Slabs 2 & 3 near Bent 1. Edge spall on Slab 3 near Bent 2. 1120-Efflorescence/Rust Staining Minor leakage with efflorescence is present through the keyways, with buildup. 511-AC Wearing Surface 523-Waterproof Membrane
Minor leakage with efflorescence is present through the keyways, with buildup. 511-AC Wearing Surface 523-Waterproof Membrane
523-Waterproof Membrane
215-Re Conc Abutment SU 1 ENV 3
225-Steel Pile SU 1 ENV 3 Concrete encased H-piles. Bent 2-Pile 1 exposed in the past, Bent 3-Pile 4 is exposed. See 10/2020 Underwater Report- details.
1000-Corrosion Bent 2-Pile 1 has minor corrosion. Bent 3-Pile 4 has corrosion with section loss.
517-Concrete Encased Per the underwater report, Bent 2-Pile 1 has 2 SF/ patched coating. Bent 2-Pile 4 has 3 SF/ of spalls. Bent 3-Pi 4 is exposed for 1ft with 5 SF/ of missing coating. All piles at Bent 3 have failing patches.
234-Re Conc Pier Cap SU 1 ENV 3 🗸
306-Other Joint SU 1 ENV 3
2310-Leakage Joints are cracked. Minor leakage through joints onto bent caps at Bents 2-4.
310-Elastomeric Bearing SU 1 ENV 3
330-Metal Bridge Railing SU1 ENV 3 All the anchor cables are missing from the end terminations.
Split auchion block at se corner

Reporting



Reporting

	End	Comments/Features	Photo #		-					-	102	2 - Ste	el Clo			Box G	iirder	r		-				
Begin				1000 - Corrosio			1010 - Cracking			1020 - Connection			1142 - Fire Damage			1900 - Distortion			7000 - Damage			518 - Steel Paint		
				CS2 470	CS3	CS4 0	CS2 3	CS3 0	CS4 0	CS2 1	CS3 1	CS4 0	CS2 0	CS3 0	CS4 0	CS2 13	CS3 0	CS4 0	CS2 0	CS3 0	CS4 0	CS2 1915	CS3 33	CS4 9
Tub B (Girder 1) -	SW spans									-	-		-			1.5						1313		-
FB110	FB109																					1		
FB109	FB108	Bolt missing on FB109 connection to bottom flange.	4052								1													
FB108	FB107																							
FB107	FB106																							
FB106	FB105	Surface rust on top flange of FB106		1																			2	2
FB105	FB104																							
F899	FB98																							
F898	FB97																							
F897	FB96																							
F896	F895																					1		
FB95	FB94	Freckied rust on top flange of floorbeam adjacent to Field Splice #15.		12																		12		
FB94	FB93	P&R. Sunace rust and paint naking.		- 4																		4		
Exp. Jt 3	FB79	Minor pigeon debris. Tack welds at pins and nuts, evidence of past rotation. Freckled rust on top flange of	5514	1																				
FB79	FB78																							
FB78	FB77																							
Exp. Jt 4	Pier 4 (Bent 14)	Evidence of rotation between the hangers and the nuts based on the paint. Hanger out of alignment 1/8" over 6" transversely. Bolt heads on eutride of source able to enco		1																		5		
Pier 4 (Bent 14)	FB38	Intersecting weld detail between lower metal bar to floorbeam diaphragm weld and diaphragm to web weld; also the intersecting weld detail is 1/2" away from the end of lower longitudinal stiffener weld.																						
Pier 2 (Bent 16)	FB20	At Pier 2, intersecting weld detail between floorbeam diaphragm to web weld and girder top flange to web weld.																						
FB14	FB13	Paint failure on Web B2 near FB13.																						4
FB13	FB12			7																				
FB12	FB11			5																				
FB11	Pier 1 (Bent 17)			5																				
Pier 1 (Bent 17)	FB10																							



- Health & Safety Plan
- Safety debriefing before each shift
 - What went well?
 - What needs to be improved?
- ANY employee at ANY time can call off the inspection for ANY safetyrelated reason






• Slips, Trips, and Falls



• Live Traffic




Safety

Low Visibility



• Fatigue







• Urban Campers







Overall Lessons Learned

- Preparation, preparation, preparation
 - Have and know your plan, but be willing to adapt on the fly



Lessons Learned

- Preparation, preparation, preparation
 - Have and know your plan, but be willing to adapt on the fly

- Always build in an extra day (or two) in the schedule
 - Expect the best, prepare for the worst



Lessons Learned

- Preparation, preparation, preparation
 - Have and know your plan, but be willing to adapt on the fly

- Always build in an extra day (or two) in the schedule
 - Expect the best, prepare for the worst

Incentives never hurt...





QUESTIONS?