Morton / **Strom Field** / 39P

Communications	Navigation
CTAF 122.9	Elevation . . . . . 941′ MSL
PCL . . . . . CTAF (For MIRL & BCN)	TPA. . . . . 1941′ MSL (1000′ AGL)
	Runway . . . . . 07/25; 1810′×40′; ASPH
	Lights . . . . . Dusk-dawn, NSTD, MIRL
	Latitude . . . . . N 46° 33.02′
	Longitude . . . . . W 122° 16.00′



Services

Fuel . . . . . None

Fly Washington Passport Program
Stamp is in clear plastic box between first and second hangar on west end.

Note: Runway is short and narrow. Pavement is in poor condition. Land at your own risk.

Notes Unattended. Displaced threshold Rwy 07 - 200' - 1610' avail. Displaced threshold Rwy 25 - 200' - 1610' available. Deer and elk on and in vicinity of runway.