Eatonville / **Swanson Field** / 2W3

Communications	Navigation
CTAF 122.9	Elevation . . . . . 843′ MSL
PCL . . . . . 122.9 (For MIRL)	TPA. . . . . 1643′ MSL (800′ AGL)
	Runway . . . . . 16/34; 2990′×36′; ASPH
	Lights . . . . . Dusk-dawn, MIRL
	Latitude . . . . . N 46° 52.30′
	Longitude . . . . . W 122° 15.43′



Services

Fuel . . . . . None

Fly Washington Passport Program mailbox is in the information booth at the drive-in entrance to the airport on the NW corner. There is a flagpole near the booth. Gravel service road around RWY 16/34 is not available for aircraft operations. Please Read Chart Supplement For Details.

Notes **Right-hand traffic on runway 16.** Watch for deer on airport. Buildings and roads close proximity to runway. Roads are not taxiways, aircraft must back taxi. On departure maintain runway heading until beyond runway threshold.