


## SR 520 pontoon repairs in a coffer cell on Lake Washington

November 2013


### STEP 1

- Launch coffer cell into Lake Washington



### STEP 2

- Lower coffer cell into lake to allow joining with pontoon.
- Install floats for stability and buoyancy.



### STEP 3

- Join pontoon and coffer cell
- Pump water from coffer cell

