

Western Bridge Engineers' Seminar 25 September 2007

John Hinman, P.E., S.E. CH2M HILL Boise, Idaho

Location Cascade Midvale Rainbow Bridge Smiths Ferry Weiser Ola Garden Valley Payette Gardena Ontario New Plymouth Sweet Horseshoe Bend O Letha Emmett Idaho City Idaho Notus Boise Na Middleton Eagle caldwell (20) 19) Nampa Meridian Boise Homedale Marsing



































- Arch Stabilization
- Column Stabilization
- Column Replacement
- Aesthetic Feature Replacement
- Repair Stringer Ends
- Replace Rails





- Preserve original fabric
- Match color, texture, and shape
- Maintenance of Traffic
- Meet structural and safety requirements



- Existing concrete reflects the source
- Desire is to match the original over the long term
- Contract item to match concrete color by adjusting cement and aggregate


Color Matching

- Composition of original aggregates
- Made samples
- Cut and polished samples to enhance color
- State selected mix
- Object is to weather toward the original color







Maintenance of Traffic



Maintenance of Traffic



Maintenance of Traffic







Stringer End Repair































Western Bridge Engineers' Seminar 25 September 2007

John Hinman, P.E., S.E. CH2M HILL Boise, Idaho