


# Hoquiam / Bowerman Field / HQM



<b>Communications</b>	<b>Navigation</b>
-----------------------	-------------------

ASOS . . . . . 135.775  
 CTAF/UNICOM 122.7  
 PCL . . . . . CTAF (For HIRL, MALSR Rwy 24;  
 REIL Rwy 06)

Elevation . . . . . 18' MSL  
 TPA . . . . . 1000' MSL (982' AGL)  
 Runway . . . . . 06/24; 5000'x150'; ASPH  
 Lights . . . . . Dusk-dawn, HIRL  
 Latitude . . . . . N 46° 58.27'  
 Longitude . . . . . W 123° 56.19'



<b>Services</b>
-----------------

Fuel . . . . . 100LL, Jet A1+ (24-hour credit card fuel services for 100LL)  
 Jet A, call 360-589-1895  
 (1700-0100Z) or 360-310-0201  
 (0100-1700Z)

<b>Notes</b>	<b>Right hand traffic on runway 06.</b> Unattended. Watch for waterfowl on and in vicinity of airport. Ultralights prohibited without written permission.
--------------	---