

Oroville / Dorothy Scott International / ØS7




Communications

CTAF 122.9
PCL CTAF (For MIRL)

Navigation

Elevation 1064' MSL
TPA 2064' MSL (1000' AGL)
Runway 15/33; 4014'x50'; ASPH
Lights Dusk-dawn, MIRL
Latitude N 48° 57.54'
Longitude W 119° 24.72'



Services

Fuel 100LL (24-hour credit card fuel services)

Fly Washington Passport Program

Stamp is in a lockbox in the new kiosk. Kiosk is on the outside of the fence. Code to lockbox is 1530. Code to re-enter the gate is 153.



Notes

Right-hand traffic on runway 15. U.S. Customs and Border protection services available (509-476-2955). Wildlife adjacent to runway and taxiway.